

Work Permit # DRL-2007-9
Work Order # _____
Job# ____ Activity# ____

ork requester fills out this section.		ork Permit				
Requester: Don Lynch	Date: 5/22/07	Ext.: 2253	Dept/Div/Group: PO/PHE	NIX		
Other Contact person (if different from requester): Carter Biggs			Ext.: 7515			
ork Control Coordinator: Don Lynch	Start Date: 5/23/07	Est. End Date: 6/30/07				
ef Description of Work: Set up, Run and	d disassemble VTX mounting vibrati	on environment test.	•			
	Room: IR & AH	Equipment: CM & HBD I-bea	am Service Provider: PHENI)	(Techs		
Requester/Designee, Service Provider	r, and ES&H (as necessary) fill ou	t this section or attach analy	rsis			
ES&H ANALYSIS						
Radiation Concerns	None	Airborne	☐ Contamination	Radiation		
Radiation Generating Devices:	Radiography	Noisture Density Gauges	Soil Density Gauges	X-ray Equipment		
Special nuclear materials involved, n	otify Isotope Special Materials Grou	ip .	☐ Fissionable materials involve	d, notify Laboratory Criticality Officer		
Safety Concerns	☐ None	☐ Ergonomics	☐ Transport of Haz/Rad Materi	al		
Adding/Removing Walls or Roofs	☐ Confined Space*	☐ Explosives	☐ Lead*	☐ Penetrating Fire Walls		
Adding/Removing Walls of Rools	☐ Corrosive	☐ Flammable	Magnetic Field* (see plan)	☐ Pressurized Systems		
Asbestos*	☐ Cryogenic	☐ Fumes/Mist/Dust*		☐ Rigging/Critical Lift		
☐ Beryllium*	☐ Electrical	☐ Heat/Cold Stress	☐ Noise*	☐ Toxic Materials*		
☐ Biohazard*	☐ Elevated Work*	☐ Hydraulic	☐ Non-ionizing Radiation*	☐ Vacuum		
☐ Chemicals*	☐ Excavation	☐ Lasers*	☐ Oxygen Deficiency*	☐ Other		
Does this work require medical clearand	ce or surveillance from the Occupati	onal Medicine Clinic? Yes	s 🔀 No	·		
Environmental Concerns		None Non	☐ Work impacts Environmental	Permit No.		
Atmospheric Discharges (rad/non-rad	q)	☐ Land Use	Soil	☐ Waste-Mixed		
	·		Activation/contamination			
Chemical or Rad Material Storage or	Use	Liquid Discharges	☐ Waste-Clean	☐ Waste-Radioactive		
Cesspools (UIC)		Management	☐ Waste-Hazardous	☐ Waste-Regulated Medical		
High water/power consumption		Spill potential	☐ Waste-Industrial	☐ Underground Duct/Piping		
Waste disposition by:				☐ Other		
Pollution Prevention (P2)/Waste Minim	nization Opportunity:	⊠ None ☐ Yes				
ACILITY CONCERNS	None					
	☐ Electrical Noise	Potential to Cause a F	alse Alarm	☐ Vibrations		
Access/Egress Limitations	☐ Impacts Facility Use Agree	ement	☐ Temperature Change	Other		
Configuration Control	☐ Maintenance Work on Ven		Utility Interruptions			
WORK CONTROLS						
Work Practices						
☐ None	☐ Exhaust Ventilation		☐ Spill Containment	☐ Security (see Instruction Sheet)		
⊠ Back-up Person/Watch	☐ HP Coverage	Posting/Warning Signs	☐ Time Limitation	☐ Other		
Barricades	☐ IH Survey	Scaffolding-requires inspection	☐ Warning Alarm (i.e. "high level")			
Protective Equipment						
None	☐ Ear Plugs	Gloves	☐ Lab Coat	☐ Safety Glasses		
☐ Coveralls	☐ Ear Muffs	Goggles	Respirator	☐ Safety Harness		
Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Covers	Safety □ Other		
				Shoes		
Permits Required (Permits must be valid		T =				
None	Cutting/Welding	Impair Fire Protection				
Concrete/Masonry Penetration	☐ Digging/Core Drilling	Rad Work Permit-RWF	² No			
Confined Space Entry	☐ Electrical Working Hot	Other				
Dosimetry/Monitoring		T ==				
None Non	Heat Stress Monitor	Real Time Monitor	☐ TLD			
☐ Air Effluent	☐ Noise Survey/Dosimeter	Self-reading Pencil Dosimeter	☐ Waste Characterization			
Ground Water	O ₂ /Combustible Gas	Self-reading Digital Dosimeter	☐ Other			
☐ Liquid Effluent	☐ Passive Vapor Monitor	Sorbent Tube/Filter Pump				
Training Requirements (List below spec	cific training requirements)					
PHENIX Awareness except untrained esc	cort form for HYTEC engineers, Elec	ct Safety 1 for PHENIX techs.				
Based on analysis above, the Walkdov ratings below:	wn Team determines the risk, com	If using the permit when all hazard ratings are low, only the following need to sign: (Although allowed, there is no need to use back of form)				
ES&H Risk Level:		High	WCC: Don Lynch	Date: 5/22/07		
Complexity Level:		☐ High	Service Provider:	Date:		
Work Coordination:		☐ High	Authorization to start Date:			
		·	(Dementers and all Comp MACC/Designs	\		

Work Plan (procedures, timing See Attached backup Documer	g, equipment, and personnel availability nee ntation	d to be addressed)	:				
Special Working Conditions Re	quired:						
Operational Limits Imposed:							
Post Work Testing Required:							
Job Safety Analysis Required: ☐ Yes ☐ No			Walkdown Required: ☐ Yes ☐ No				
Reviewed by: Primary Review	ver will determine the size of the review tear	m and the other sig	natures required b	ased on hazards	s and iob complexit	v. Primary Reviewer signature means	
Reviewed by: Primary Reviewer will determine the size of the review team and the other signatures required based on hazards and job complexity. Primary Reviewer signature me that the hazards and risks that could impact ES&H have been identified and will be controlled according to BNL requirements.							
<u>Title</u>	Name (print)	<u>Signature</u>		Life #		<u>Date</u>	
Primary Reviewer ES&H Professional							
Other							
Other							
Work Control Coordinator							
Service Provider	_	_					
	Review Done: in series	☐ team					
ob site personnel fill out this sec	tion.						
Note: Signature indicates person	onnel performing work have read and under	rstand the hazards	and permit require	ements (including	g any attachments).		
Job Supervisor:			Contractor Supervisor:				
Workers:	Life#:		Workers:		Life#:		
Workers are encouraged to provide feedback on ES&H concerns or on ideas for improved job work flow. Use feedback form or space below.							
epartmental Job Supervisor, Wo	rk Control Coordinator/Designee						
Conditions are appropriate to start work: (Permit has been reviewed, work controls are in place and site is ready for job.)							
Name:	Name: Signature:		Life#:		Date:	Date:	
onartmental Joh Supervisor We	rk Requester/Designee determines if Po	et Joh Poviou is r	aguired D Voc	. I No			
Post Job Review (Fill in names		St Job Review is i	equileu. 🔲 165	NO NO			
Name:	Signature:		Life#:		Date:		
Name:	Signature:					Date:	
	1 3 1 11						
Vorker provides feedback. Worker Feedback (use attached a) WCM/WCC: Is any feedback							
b) Workers: Are there better m	nethods or safer ways to perform this job in	the future? \(\subseteq \text{ Ye}	es 🗌 No				
oseout: Work Control Coordinat n up of work area to work superv	tor (authorizing dept.) checks quality of original controls (completed permit	and ensures the	work site is left	in an acceptable	condition. (WCC can delegate	
Name:	Signature:		Life#:		Date:		
Comments:	1				1		

VTX Mounting vibration test

Purpose

In order to appropriately evaluate the vibration isolation requirements for the VTX support structure, HYTEC engineers propose to measure the vibration background environment under simulated operating conditions of the PHENIX detector. This is to be accomplished during a 4 hr. (minimum) maintenance access, during which time accelerometers will be attached to the existing HBD support structure, wired to readout electronics, CM magnets will be energized to full field with cooling water circulating at nominal flow rates. The data thus acquired will be analyzed and used as a baseline for the VTX support structure vibration environment.

Work Plan

This work is to be done by fully trained and experienced PHENIX mechanical and electrical technicians under the guidance of Robert PAK, PHENIX scientist who will be escorting HYTEC engineers to be present as observers/advisors.

- 1. Prior to the access, PHENIX mechanical techs will prepare an aluminum block with 3 accelerometers mutually orthogonally mounted with 5 minute epoxy and machined to be attached to existing tapped holes on the southwest and northwest lower HBD mounting bracket.
- 2. After access is granted by the RHIC Control Room, All PHENIX magnets will be turned off
- 3. PHENIX mechanical techs will move the West Carriage to the retracted position.
- 4. The accelerometer block will the be fastened to the northwest lower HBD mounting bracket.
- 5. Accelerometer cables (~10' long) will be connected to the 3 accelerometers and the other ends to an amplifier to be securely mounted (strapped) in one of the CM base cubby holes
- 6. ~100 feet of signal cable will then be connected to the amplifier and routed through the plug door to an appropriately located table containing the HYTEC readout electronics in the AH. (Note: connected to 110v AC)
- 7. PHENIX mechanical Techs will then sweep the IR and make sure that no personnel are in the IR and noone will be permitted to enter the IR while magnets are on.
- 8. All PHENIX magnets will be unlocked and energized with cooling water flowing at nominal rates.
- 9. After HYTEC engineers have determined that enough data has been accumulated, all PHENIX magnets will be turned off and locked out.

- 10. The accelerometer block shall be unfastened from the lower northwest HBD mounting bracket and fastened to the south west HBD mounting bracket.
- 11. Steps 7 through 9 shall then be repeated.
- 12. All amplifiers, electronics, cables, accelerometers and mounting blocks shall be removed from the IR and any HBD mounting hardware displaced for this test shall be returned to its condition prior to the test.

Any deviation from the above sequence requires prior approval of the designated PHENIX Work Control Coordinator and shall be documented in the Work Permit Closeout section.